

AL028 Battery discharge EVD

SPRSUN



Cause analysis

The unit has strong electric interference

Detection method

There are other electrical equipment nearby that have large electromagnetic interference

Solution

Isolate the power equipment and restart after 3 minutes of power failure.