

AL053 Power+ alarm:03-DCbus overvoltage **SPRSUN**

AL054 Power+ alarm:04-DCbus undervoltage

Cause analysis

The voltage is too high or too low

Detection method

Use a multimeter to measure the actual voltage over or under the rated voltage by more than 20%

Solution

Add a voltage regulator, or find a power supply bureau to keep the voltage stable