


AL114 Power+ alarm: Power+ offline

Cause analysis


- The interval between power-off and power-on is too short
- The position of the inverter's dialing switch is wrong, and the direction of the inverter's dialing must be the same




AL114 Power+ alarm: Power+ offline

Cause analysis

- Inverter cable is loose



Main control board connection line




380V frequency converter
communication line

AL114 Power+ alarm: Power+ offline

Cause analysis

- Inverter cable is loose



220V frequency converter communication line

AL114 Power+ alarm: Power+ offline

SPRSUN

Solution

- If the power-on interval is too short, it can be powered off again and wait 3mins to power on. If it still fails, it can be powered off for 10 minutes
- Dial the dip code on the inverter to the same level
- Re-tighten the inverter connection cable